

PCB IN - PCB OUT AIRCONDITIONING SPARE PARTS



B1 QUANTITY A250-180 E56334 3 JAC01 A/S 228 42QP4B5850L4 1 AYU901-1385G00 1 MAIN SAB REV C CS 4 SISME GROUP 1 C022632H05 CESS230012 1 C023444H01 1 BITRON MODULE 50-03 524782-5 4 LUM REG V3 1 JAQ1 AS 231 42QP4B5850L4 1 C022631H04 CESS230010-IC 1 CARRIER MARINE C025057H01 NTC 42DWC_K 1 CARRIER MARINE C023731H01 1 CARRIER B035020H01 1 ASM 6871AQ2178 1 C02363H01 1 COD 0352207H10 1 A2516-210 1 J423320B LOGIKA CONTROL 1 CMC 880.1 2 438800 REV 1 1 UC REG V3 1 MTA-JT 1 LUM 2X2V 1 ECA 920 1 B2 QUANTITY CARRIER MARINE C023731H01 11 CEPM 430001-05 CESH430001-05 1 CEPL130567-03-R CARRIER 1 "Hitachi inverter air conditioner board computer 17B32998H 17B33614A PI024-4 Board " 1 KKW 451501.28.84 6 FUJI ELECTRIC 6DI50M-050 1 MTA 3V 2 LUM 2X2V 2 LUM REG V3 2 CAC CTRL REV 0.7 1 CARRIER C0233525H01 1 honeywell W4115B 1 03D01XX 2 SISME GROUP 1 BITRON MODULE 50-03 524782-5 2 CARRIER PBC C022631H01 CEPL130010-02 1 JH07 A/S 887 42QH5A5850HX 1 JG07 A/S 321 42QP8B5850FY 1 JAC01 AS 222 42QP4B5850L4 1 BITRON MODULE 50-03 524782-5 1 B10250-100 MAIN LCD 1 B3 QUANTITY ar20 ct/e/109 1 CE-KFR48G/Y-E1 2 STORE REG V3 1 MTA-JT 1 SISME GROUP 1 LUM REG V3 1 LUM 2X2V 1 PCB05-34-V02 2 C022631H04 1 CESS230010 1 REV-E-PS MAIN SAB 3 C025057H01 1 SCM028 REV.4 1 AIRWELL 121853 1 GEN CONTROL REV 0.5A 1 LUM REG V3 3 JAC01 AS 233 42QP4B5850L4 1 DERWENT COR245 1 BITRON MODULE 50-03 524782-5 2 CLIVET 000630071B 1 J423320B LOGIKA CONTROL 1 MCC-5046-02 1 A2516-210 1 E122808 1 CARRIER 0170307H22 1 MCS 100 C023325H01 1 C024374H01-R 1 EURUKA CL9210 1 A2520-180 1 JAC01 AS 1303 42QP4B5850 1 JAC01 AS 232 42QP4B5850 1 JH07 A/S 885 42QH5A5850 1 PWB 6870AQ2175A-3 1 HPI INPUT FILTER 1 MTA-3V 1 B4 QUANTITY A2516-210 5 COLDCOROLLA 1 ECS BELLUNO 1 A2520-180 4 ECS BELLUNO 000630033A 1 KKW 451501 28.84 8 SISME GROUP 3 A2516-210 1 STORE REG V3 2 JG07 A/S 341 42QP85850FY 1 CARRIER PBC C022631H01 CEPL130010-02 1 LOGIKA

?????????????: ??? ?????????????? ??????
?????

[???????? ?? ? ? ??????](#)

??????????